

Equipment Technical Bulletin

Blank Pixel Row on Summit E/XL Programmer



PROBLEM

As shown the picture, row(s) and/or columns on a small percentage of E/XL Programmers can be missing.

Unit operation is not affected. Programmer works normally but does not display some pixels.

SCOPE

This problem appears to be specific to certain recent production lots of LCD's from our vendor with 4% or less showing this problem.

SOLUTION

Do one of the following:

1. Use the Programmer as is. Operation is not affected.
2. Return Programmer to Beta for a free warranty replacement.



BLANK PIXEL ROW



Beta Technology
2841 Mission Street
Santa Cruz • CA
U.S.A. • 95060-2142

TEL • 831 • 426 • 0882
TEL • 800 • 858 • 2382
FAX • 838 • 423 • 4573
FAX • 800 • 221 • 8416

Beta Technology is ISO9001 Certified