

600 Series Pump Cartridge Assemblies

Equipment Technical Bulletin



Equipment Technical Bulletin February 16, 2001

Dear Valued Customer,

Some units which shipped between January 5th and February 15th of 2001 may lack lubrication on the 600 series pump cartridge rollers. Units effected include Modulus, LS3000, and any spare 600 series pump cartridge assemblies. This could lead to premature roller failure. In the event you may have received one of these defective rollers, we are sending you replacement roller assemblies.

Thank you for your patience.