

# Equipment Technical Bulletin

## 100 Series Large Detergent Flex and Detergent Flex Now Have Stainless Steel Clamps



---

### PROBLEM:

Tie wraps were not strong enough to cinch the tube down onto the small SnapHead barb. In some cases product would then not feed.

### SOLUTION:

Tie wraps have been replaced with stainless clamps. Item numbers remain the same.



**Beta Technology, Inc**  
2841 Mission Street  
Santa Cruz • CA  
U.S.A. • 95060

TEL • 831 • 426 • 0882  
TEL • 800 • 858 • 2382  
FAX • 831 • 423 • 4573  
FAX • 800 • 221 • 8416  
TEL (U.S. and Canada) • 800 • 468 • 4893  
TEL (outside U.S. and Canada) • 410 • 228 • 1292  
sales@beta-technology.com

Customer Service

Tech Support

**Beta Technology, Inc**  
4 Finway, Dallow Road  
Luton LU1 1TR  
United Kingdom

Freephone • 0800 • 052 • 4726  
Tel • +44(0) • 1582 • 528600  
Fax • +44(0) • 1582 • 528111  
Freephone • 0800 • 052 • 4726  
VAT REG.NO.BG.354 - 09975 - 44  
europe.sales@beta-technology.com

Customer Service

Tech Service

Online Ordering: <http://www.beta-technology.com>