

Equipment Technical Bulletin

Summit Flush Manifold-Flow Switch/Manifold Pipe Connector




PROBLEM

The fitting that connects the flow switch to the manifold pipe breaks easily if installation instructions are not followed precisely.

SOLUTION

All units are now being produced with a brass connector, which is extraordinarily robust. Units which already shipped with the plastic connector are usable, but care needs to be taken during installation to follow the installation instructions carefully, since twisting the connector the wrong way can easily break the bracket.



Beta Technology, Inc
2841 Mission Street
Santa Cruz • CA
U.S.A. • 95060

TEL • 831 • 426 • 0882 |
TEL • 800 • 858 • 2382 |
FAX • 831 • 423 • 4573 |
FAX • 800 • 221 • 8416 |
TEL • 800 • 215 • 6415 | Tech Support
sales@beta-technology.com

Customer Service

Beta Technology, Inc
4 Finway, Dallow Road
Luton LU1 1TR
United Kingdom

Freephone • 0800 • 052 • 4726 |
Tel • +44(0) • 1582 • 528600 | Customer Service
Fax • +44(0) • 1582 • 528111 |
Freephone • 0800 • 052 • 4726 | Tech Service
VAT REG.NO.BG.354 - 09975 - 44
europe.sales@beta-technology.com

Online Ordering: <http://www.beta-technology.com>