

# Equipment Technical Bulletin

## Clog-Resistant Check Valve Parts Now Ultrasonically Welded Together

---

### PROBLEM:

The clog-resist check valve used on the large laundry manifold (code number 1201123) and the OPL manifold (code number 1202892) consists of three separate components and can be difficult to assemble.

### SOLUTION:

We are now ultrasonically welding the check valve components together. The new item number for the spare check valve is 1203747. The spare check valve and manifolds bearing the new check valve will start shipping from Santa Cruz in February. Luton and Cambridge will have the spare check valve available shortly thereafter.



*Old Check Valve Assembly*



*New Check Valve Assembly*